

MELTING BALM

FASE	INGREDIENTI	FORNITORE	INCI	(wt-%)
A	SUNFLOWER WAX	Yokozeki Oil & Fat Industries	Helianthus Annuus (Sunflower) Seed Wax	4,50
	SUNFLOWER BUTTER	Yokozeki Oil & Fat Industries	Sunflower Seed Oil/Hydrogenated Sunflower Seed Oil Esters	5,00
	S-FACE IS-204P MB	Sakamoto Yakuhin Kogyo	Polyglyceryl-2 Tetraistearate	67,10
	S-FACE VL-211 MB	Sakamoto Yakuhin Kogyo	Macadamia Seed Oil Polyglyceryl-6 Esters Behenate	5,00
	VISTANOL GDHR	Seiwa Kasei	Glyceryl Diisostearate/ Hydrogenated Rosinate	10,00
	ORYZA OIL S-1	Oryza Oil&Fat Chemical	Oryza Sativa (Rice) Germ Oil	5,00
	RE:LAMEIL	Tribauté	Glycolipids	0,10
B	PEARL STARCH (L)	Japan Corn Starch	Zea Mays (Corn) Starch, Zinc Stearate	3,00
C	PERFUME		Fragrance	0,30
			Total	100,00

1/ Pesare tutti gli ingredienti della fase A e metterli nel recipiente principale, quindi fondere a 78-80° C.

2/ Aggiungere la fase B alla fase A a 80° C e disperdere.

3/ Aggiungere la fase C al lotto principale (fase A+B) a 65° C e disperdere.

4/ Inserire la miscela in una confezione idonea e raffreddare il lotto a temperatura ambiente.